The natural ventilation system 1960s building shell retained 2 new glazed screen and environmental buffer zone on north side new sunshade screen on south side existing pivoted windows new holes cut through floors and roof new openable rooflights wind 5